

TOWNSHIP 33 RANGE 07 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 (DCSO records Vol. 21 Page(s) 9056)

Set a granite stone 22 x 8 x 6 ins., 17" in the ground, for 1/4 sec. corner, marked 1/4 on W. face, from which

A Chinquapin 4" dia., bears S.59°E., 64 lks. dist., mkd. 1/4 S8 BT.

A Fir 50" dia., bears S.1°W., 474 lks. dist., mkd. 1/4 S7 BT.

This corner stands 400 ft. above sec. corner.

BLM remonumentation survey by Joseph S. Gawron, Cadastral Surveyor, under instructions dated May 1957, Group #350, surveyed May/June 1966 (DCSO records Vol. 34 Page(s) 14135)

The 1/4 sec. cor. of secs. 7 & 8, monumented with the broken orig. granite stone, 22"x8"x6", firmly set, 10" in the ground, mkd. 1/4 on W. face, from which the remaining orig. BT:

A Fir, 56" dia., bears S.1°W., 476 lks., mkd: 1/4 S7 BT on a bark blaze. (Rec. 474 lks.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 33 S R 7 W

1/4

S 7 S 8

1966

from which the new bearing trees

A live Oak, 6" dia., bears S.27°E., 25 lks., mkd: 1/4 S8 BT.

A Fir, 18' dia., bears N.16°W., 136 lks., mkd: 1/4 S7 BT.

Deposit corner stone alongside iron post.

Cor. Fd. and used in BLM resurvey by Roseberry and Aanrud, under Group #845, surveyed April/Nov. 1975 (DCSO records, Vol. 41 Page 16285)