

TOWNSHIP 33 RANGE 07 POINT IDENTIFIER # 200640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 (DCSO records Vol. 21 Page(s) 9060)

Set a granite stone 18 x 9 x 6 ins., 12" in the ground for 1/4 sec. corner, marked 1/4 on W. face, from which

A Laurel 10" dia., bears S.43°E., 34 lks. dist., mkd. 1/4 S5 BT.

A Fir 12" dia., bears N.30°W., 7 lks. dist., mkd. 1/4 S6 BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, W. Penley, crew - May/June 1968 - C.S. File 54/36-180

Found - No trace of corner stone.

10" now 12" Laurel S.43°E., 22.4 ft. open and shows scribing.

12" now 18" D.Fir N.30°W., 4.6 ft. shows bark scribing.

Set Brass cap at cor. mkd: County Surveyors Office

T 33 S R 7 W

1/4 S 6 | S 5

1968

Rescribe-18" D.Fir N.30°W., 4.6 ft. scribed 1/4 S6 CS BT.

This 1/4 corner lies North-South cutting line and 360 ft. South of a creek.

Dane Meade - For: Silver Butte Timber Co. - 3/2024 - M183-52

Found 1968 Douglas Co. Surveyor brass cap & BTs per record.