

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 (DCSO records Vol. 21 Page(s) 9049)

A Fir 14" dia., for ¼ sec. corner, I marked ¼ S8 on W. side, and 9 on E. side, from which
A Fir 18" dia., bears East, 3 lks. dist. mkd. ¼ S9 BT.
A Fir 14" dia., bears S.48°W., 22 lks. dist. mkd. ¼ S8 BT.
This corner stands 150 ft. below dividing ridge.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, W. Penley, crew - May/June 1968 - C.S. File 54/36-162

Found - 14" D.Fir corner tree, now 16", good scars on E-W face.
18" D.Fir, now snag, East 2.0 ft., opened for scribing "S"
14" D.Fir now 12 ft. high stob, S.48°W., 14.5 ft.
Set Brass cap on W. side of 17" corner tree, mkd:
County Surveyors Office
T 33 S R 7 W Doug.
¼ S 8 | S 9 Co.
Jos. Co. 1968
New BTs -26" D.Fir S.35°W., 20.0 ft. mkd. ¼ S8 CS BT.
39" D.Fir N.20°E., 25.1 ft. mkd. ¼ S9 CS BT.

BLM resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #845, surveyed April/Nov. 1975 (DCSO records Vol. 41 Page(s) 16283)

The ¼ sec. cor., monumented with the original corner tree, a Fir snag, 16" dia., with healed blazes on E. and W. sides, from which the remains of the original bearing trees:
A Fir snag, 18" dia., bears East, 5 lks. dist., with scribe mark S visible on opened blaze. (Rec. 3 lks.)
A Fir snag 17" dia., bears S.48°W., 24 lks. dist., with healed blaze. (Rec. 22 lks.)
and the remains of bearing trees and an iron pipe mkd. by Powell in 1968:
A Fir 39" dia., bears N.20°E., 37 lks. dist., with scribe marks ¼ S9 CS BT visible on partially healed blaze.
A Fir snag 24" dia., bears S.35°W., 30 lks. dist., with scribe marks ¼ S8 CS BT visible on partially healed blaze.
An iron pipe 1¼" dia., firmly set, projecting 8" above ground, bears West, 1½ ft. dist., with brass cap mkd:
COUNTY SURVEYORS OFFICE DOUG. CO. JOS. CO. T33S R7W ¼ S8 S9 1968.
(Cont. Next Page)

TOWNSHIP 33 RANGE 07 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

and a new bearing tree:

A Fir 29" dia., bears S.40°W., 60 lks. dist., mkd. ¼ S8 BT.

Douglas Co. Surveyors Office - Randall Smith, Deputy and Stephen Flause, crew - Oct. 20, 1992 - C.S. File 64/32-17

Found - 2½" dia., 1968 DCSO brass cap on a 1½" O.D. I.Pipe protruding 8" above ground.

14" now 16" dia., 2 ft. high stump, no marks visible (orig. cor. tree). DCSO BC/IP bears West 1.0 ft. from corner tree (agrees w/1975 BLM survey)

18" now 14" D.Fir snag with scribe mark visible "S" has a healed lower blaze, bears East 3.3 ft. (agrees w/1975 BLM rec.) Orig. BT.

14" now 15" dia., D.Fir snag with a healed blaze, bears S.51°W., 15.8 ft. (Rec. S.48°W., 15.8 ft.) Orig. BT.

26" now 24" dia., D.Fir with a partially healed single blaze, scribing visible "¼ S8 CS BT" bears S.35°W., 19.5 ft. (Rec. S.35°W., 19.8 ft.)

39" now 42" dia., D.Fir with a fully healed single blaze bears N.20°E., 24.4 ft. (agrees w/1975 BLM rec.)

1975 BLM BT S.40°W., 39.6 ft. is gone.

New BTs -4" Madrone bark scribed "¼ S8 CS BT" bears S.56°W., 19.2 ft.

19" D.Fir single blazed "¼ S9 CS BT" bears N.45°E., 50.5 ft.

Corner lies in a steep slide area approx. 50 ft. West of road.