

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 9044)

Set Laurel post 3 ft. long, 3" sq., 18" in the ground, mkd. 1/4 S. on W. side, for the 1/4 sec. cor. from which
A Laurel 8" dia., bears N.15°W., 53 lks. dist., mkd. 1/4 S BT.
A Laurel 8" dia., bears N.52°W., 95 lks. dist., mkd. 1/4 S BT.

Survey by Norman D. Price - For: Dollar and Patterson Lumber Co. - March/Aug. 1954 - C.S. File 41/301

There is no remaining evidence of the original 1/4 sec. corner. Set an Iron pipe, 3 ft. long, 1 1/2" dia., 28" in the ground, mkd. RS33, from which
A D.Fir 20" dia., bears S.64°E., 10 lks. dist., mkd. 1/4 S3 RS33 BT.
A D.Fir 15" dia., bears N.89°W., 9 lks. dist., mkd. 1/4 S4 RS33 BT.

Fd. OK, DCSO, J. Powell, Feb. 29, 1968, C.S. File 54/36-182

BLM resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #845, surveyed April/Nov. 1975 (DCSO records Vol. 41 Page(s) 16276)

The 1/4 sec. cor., reestablished by proportionate measurement by Price in 1954, monumented with an iron pipe, 1 1/2" dia., firmly set, projecting 12" above ground, with brass washer mkd. RS33. There is no remaining evidence of the original corner; therefore, this position is accepted as the corner, from which bearing trees mkd. by Price:

- A Fir 29" dia., bears S.64°E., 10 lks. dist., with healed double blaze.
- A Fir 17" dia., bears N.89°W., 9 lks. dist., with healed double blaze.

At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, directly over iron pipe, with brass cap marked

T 33 S R 7 W
1/4
S 4 | S 3
1975

from which a new bearing tree
A Fir 15" dia., bears N.32 3/4°W., 40 lks. mkd. 1/4 S4 BT.
