

TOWNSHIP 33 RANGE 07 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 9037-38)

Set a Fir post 4 ft. long, 4" sq., 2 ft. in the ground marked 1/4 S on N. side, for the 1/4 sec. corner, from which

A Fir 15" dia., bears S.30°W., 26 lks. dist., mkd. 1/4 S BT.

A Laurel 12" dia., bears N.3°W., 34 lks. dist., mkd. 1/4 S BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Mike Darby and Wm. Stoffel, crew - Jan. 1963 - C.S. File 52/140-2

Found - 1 1/4" shaft at corner.

Orig. 15" now 20" partly rotted Fir stump that shows good bark scribing.

Also find clump of Laurels that checks for orig. NW BT.

New BTs -7" R.Fir bears S.34°W., 30.4 ft. scribed 1/4 S11 CSBT

13" R.Fir bears N.73°E., 11.4 ft. scribed 1/4 S2 CS BT

Fd. OK, by David Stringer, L.S. #1956, August 1983 - M 94-69

FD. OK by Lloyd Smith, 3/85, M 98-47