

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 9028-29)

Set Oak post, 3 ft. long, 3" sq., 18" in the ground, for the 1/4 sec. cor. mkd. 1/4 S on the W. face, from which
An Oak 14" dia., bears N.43°W., 87 lks. dist. mkd. 1/4 S BT.
An Oak 18" dia., bears N.35°W., 87 lks. dist. mkd. 1/4 S BT.

BLM resurvey by John Jelley, Rollin Aanrud, and Lynn Roseberry, Cadastral Surveyors, under Group #'s 350 and 688, surveyed May 1969/March 1970 (DCSO records Vol. 35 Page(s) 14476)

The 1/4 sec. cor. of secs. 13 and 14, determined at record bearing and distance from the original bearing trees:

An Oak snag 20" dia., bears N.43°E., 69 lks. dist., with scribe mark 1 visible on open blaze.

A root hole bears N.35°W., 87 lks. dist., with a down Oak 18" dia., alongside, with no marks visible.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked

T 33 S R 7 W
1/4
S 14 S 13
1969

from which new bearing trees

A Fir 8" dia., bears N.76 1/2°E., 30 lks. dist., mkd. S13 BT.

A Fir 7" dia., bears N.38°W., 21 lks. dist., mkd. 1/4 S14 BT.