

PRIMARY CORNER DESCRIPTION Sec Cor for 11, 12, 13 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 9029)

Set Chinquapin post 4 ft. long, 4" sq., 2 ft. in the ground, for the corner to secs. 11, 12, 13 and 14, marked T33S R7W S12 on NE.; S13 on SE.; S14 on SW.; and S11 on NW.; faces, also 4 notches on S. and 1 notch on E. edges, from which
A Fir 16" dia., bears N.25°E., 21 lks. dist., mkd. T33S R7W S12 BT.
A Fir 18" dia., bears S.72°E., 20 lks. dist., mkd. T33S R7W S13 BT.
A Fir 20" dia., bears S.42°W., 16 lks. dist., mkd. T33S R7W S14 BT.
A Fir 12" dia., bears N.46°W., 42 lks. dist., mkd. T33S R7W S11 BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Mike Darby and Wm. Stoffel, crew - Jan. 1963 - C.S. File 52/140-1

Found - Orig. 20" now 28" R.Fir S.42°W., 10.6 ft., shows scars.
Orig. 18" now 26" R.Fir S.72°E., 13.2 ft. shows bark scribing "BT".
Orig. 12" now (?) R.Fir N.46°W., 27.7 ft. previously opened, shows scribing.
Orig. 16" now (?) R.Fir N.25°E., 13.9 ft.
Set Brass cap at cor. mkd: County Surveyors Office
T 33 S R 7 W
S 11 | S 12
S 14 | S 13
1963
New BTs -Rescribe orig., now 28" R.Fir S.42°W., 10.9 ft. mkd. S14 T33S R7W CS BT.
Rescribe orig., now 26" R.Fir S.73°E., 12.4 ft. mkd. S13 T33S R7W CS BT.
Rescribe orig., now 21" R.Fir N.25°E., 15.5 ft. mkd. S12 T33S R7W CS BT.

BLM resurvey by John Jelley, Rollin Aanrud, and Lynn Roseberry, Cadastral Surveyors, under Group #'s 350 and 688, surveyed May 1969/March 1970 (DCSO records Vol. 35 Page(s) 14477)

The Sec. cor., perpetuated and recorded by Byron in 1963, monumented with an iron pipe 1" dia., firmly set, projecting 14" above ground, with 1963 brass cap.
(Cont. Next Page)

TOWNSHIP 33 RANGE 07 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Sec Cor for 11, 12, 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the original bearing trees

A Fir 20" dia., bears N.25°E., 23½ lks. dist., with illegible scribe marks visible on burned bark blaze. This tree remarked by County Surveyor. No marks visible on pitched over blaze. (Rec. 21 lks.)

A Fir 28" dia., bears S.73°E., 18½ lks. dist., with scribe marks T33S visible on bark blaze. This tree remarked by County Surveyor. No marks visible on pitched over blaze. (Rec. S.72°E., 20 lks.)

A Fir 30" dia., bears S.42°W., 16 lks. dist., no marks visible. This tree remarked by County Surveyor. Blaze healed.

A Fir 18" dia., bears N.46°W., 43½ lks. dist., with scribe marks S11 visible on open blaze. (Rec. 42 lks.)

I add marks BLM 1969 to brass cap.