

TOWNSHIP 33 RANGE 07 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 9030-31)

A Fir tree, 16" dia., which I marked $\frac{1}{4}$ S on a W. face for the $\frac{1}{4}$ sec. cor., from which

A S.Pine 26" dia., bears N.75°W., 30 lks. dist., mkd. $\frac{1}{4}$ S BT.

A S.Pine 24" dia., bears S.85°E., 15 lks. dist., mkd. $\frac{1}{4}$ S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, W. Penley, crew - March 4, 1968 - C.S. File 54/36-168

Found - Orig. 16" now 28" D.Fir corner tree, shows good scar on west side.

Orig. 24" S.Pine now stump S.85°E., 9.9 ft. opened for scribe "BT"

Orig. 26" S.Pine now down and rotten, N.75°W., 19.8 ft.

Set Brass cap on W. side of corner tree mkd:

County Surveyors Office

T 33 S R 7 W

$\frac{1}{4}$ S11|S12

1968

New BTs -19" D.Fir N.58°E., 13.0 ft. mkd. $\frac{1}{4}$ S12 CS BT.

6" Chinquapin N.18°W., 19.0 ft. mkd. S11 CS BT.