

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 12 and 13

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 21 Page(s) 9030)

Set Fir post 3 ft. long, 3" sq., 18" in the ground, for ¼ sec. corner, marked ¼ S on N. face, from which
A Fir 30" dia., bears S.2°E., 29 lks. dist., mkd. ¼ S BT.
A Fir 42" dia., bears N.18°E., 70 lks. dist., mkd. ¼ S BT.

Survey by T.A. Mehl, III - For: Robert Dollar Co. - June 1967 - C.S. File 55/42

Found - Orig. 30" Fir now stump hole, S.2°E., 29 lks.
Orig. 42" Fir now 48" short stump, N.18°E., 70 lks.
Orig. called distances between the creek agree closely on line.
Set 1½" iron pipe, from which
20" D.Fir N.48°57'W., 14.80 ft. mkd. ¼ S RS749 BT.
18" D.Fir N.07°48'W., 46.30 ft. mkd. ¼ S RS749 BT.

BLM resurvey by John Jelley, Rollin Aanrud, and Lynn Roseberry, Cadastral Surveyors, under Group #'s 350 and 688, surveyed May 1969/March 1970 (DCSO records Vol. 35 Page(s) 14477-78)

The ¼ sec. cor., perpetuated and recorded by Mehl in 1967, monumented with an iron pipe, 1½" dia., firmly set, projecting 10" above ground, from which the remaining original bearing tree:

A decayed Pine stump 48" dia., bears N.18°E., 70 lks. dist. with no marks visible. (Rec., a Fir) and bearing trees by Mehl
A Fir 21" dia., bears N.49°W., 22½ lks. with pitched over blaze.
A Fir 18" dia., bears S.8°W., 70 lks. dist., with pitched over blaze.

At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, with brass cap marked
T 33 S R 7 W
¼ S 12
S 13
1969

Deposit iron pipe alongside the iron post.