

Dependent Resurvey of a Portion of Donation Land Claim No. 45,
T. 22 S., R. 7 W., Willamette Meridian, Oregon

CHAINS

An oak, 14 ins. diam., bears N. 37° E., 26½ lks. dist., with partially healed blaze.

An oak, 20 ins. diam., bears S. 30¼° E., 39½ lks. dist., with healed blaze. (Record, S. 28° E., 42 lks.)

An oak, 21 ins. diam., bears S. 47° W., 73½ lks. dist., with healed blaze.

An oak, 15 ins. diam., bears N. 73° W., 69 lks. dist., with healed blaze. (Record, 170 lks.)

Set a metal fence post alongside the iron post.

Corner is located in a large blackberry patch.

Subdivision of Section 28,
T. 22 S., R. 7 W., Willamette Meridian, Oregon

From the 1/4 sec. cor. of secs. 28 and 33, reestablished by proportionate measurement by Wilford N. Haines, Registered Professional Land Surveyor No. 239, in 1961, recorded in the Douglas County Surveyor's Office map file M38-69, this position was perpetuated by Gary L. Langlitz, Deputy County Surveyor, in 1976, recorded in the Douglas County Surveyor's Office corner renewal file, T. 22 S., R. 7 W., point identifier No. 340200. There is no remaining evidence of the original corner, therefore this position is accepted as the corner; monumented with an iron post, 1½ ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

DOUGLAS CO. SURVEYOR
T 22 S
R 7 W
S 28
1/4 ———
S 33
1976

from which a bearing tree and an accessory mkd. by Haines

A fir, 21 ins. diam., bears N. 23 3/4° E., 15½ lks. dist., with healed double blaze.

A bridge spike, set flush in the center of a rotted sawed fir stump, 61 ins. diam., bears S. 17½° E., 19½ lks. dist.

and the remains of a bearing tree mkd. by Langlitz

A rotted fir stump, size indeterminate, bears S. 58° W., 11 lks. dist., no marks visible.

and an accessory set by person(s) unknown and recorded by Langlitz

A rebar, 5/8 in. diam., firmly set, projecting 7 ins. above ground, bears S. 45½° E., 5 lks. dist.