

FIELD NOTES

T22 R9

DONATION LAND CLAIMS

CHAINS

T 223 R9W DLG # 37
T 223 R10 W DLG #37

va. 20° 00' E

22.00

I make diligent search and find the stump of the fir 48 ins. diam with the letters very distinct; also the maple now 24 ins. dia but the letters have decayed.

I set a fir post 4 in square 4 ft. long 24 ins. in the ground at place marked N W Cl. 37.

The fir stump now 55 ins. diam bears S 30PE 38 lks. dist.

Marked C L 37 B.T.

I also remark the maple now 24 ins diam.

N. 3 E 71 lks. dist.

Cl. 37 B. T.

From this re-established cor I run

South on the west boundary of claim 37.

va 20° 00' E

4.35

A creek 25 lks wide course SSE

5.35

Same creek 25 lks wide course 3SW

6.15

Same creek 25 lks wide course SSE

21.00

Old road course E and W

21.60

To right bank of Umpqua river.

Former location of corner; has been washed way.

And I cannot find any definite trace of bearing tree stumps as all the timber has been cut away.

At 21.50 I set a temporary cor. but do not mark any bearing trees as the land on both sides of the line belongs to the same parties.

The storm is so severe that I cease work for the day

Nov 13, 1896.

I now begin at the N W cor of claim 37 just re-established and run thence

N 70° 45' E on north boundary of Claim 37

Va. 20° 00' E.

Steep irregular ascent.