

County Surveyor's Record, Douglas County, Oregon

FIELD NOTES

T22 R9

DONATION LAND CLAIMS

CHAINS

T22S R9W DLC #38

Thence L run East on the south boundary
of claim 38. Va. 20°00' E.

To obtain distance across the river I place a flag
on line on left bank of river. I now measure a
5 ch. for base, S end of base the flag
South bears N 62°E making the angle of the plane triangle
~~triangle~~ at South end of base 62 therefore the
distance is $\tan. 62 - X \text{ base}$ or $1.804 \times 5.00 = 9.40$
chs the distance

9.40 from cor to the flag on the East or left bank of
river.

11.00 Steep ascent top of bluff on bench 40 ft. above river.

15.00 Begin steep ascent.

30.00 Top of steep ascent 400 ft. above bench thence along
slope

33.00 Cannot find any definite trace of claim corner.

I now return to the ^N E cor of claim 37

Thence I run S 70°45' W on S body of
claim 38. Va 20°00' E

1.00 Road to Scottsburg course N & S.

1.40 Fence and field course N and S.

5.10 Foot of hill and fence course N E and S W leave
field steep ascent.

23.00 To S W cor of claim 38.

The burnt fir 24 in diam bears N 65-W 30 lks dist
is still standing.

The other bearing tree is not here - probably burned.

I set a fir post 4 ins square 4 ft long 24 ins in the
ground for S W cor of claim marked Cl. 38 - from
which A fir 6 ins diam bears S 56°E 44 lks.

distance marked Cl. 38 B. T.

Thence I run North on the West boundary of
Claim 38 va. 20°00' E.

8.85 A branch 4 lks wide course S E.