

County Surveyor's Record, Douglas County, Oregon

FIELD NOTES

T22 R9

DONATION LAND CLAIMS

CHAINS

T223 R9W DLC #38

45.00 Top of rise on west slope 400 feet above river bottom.

53.50 begin descent.

56.72 From this point which is near the intersection with my East and West line, I find a fir now 36 in dia with a burnt side facing N 20°W which could scarcely have been caused by any other than the blaze of a bearing tree and for additional evidence of this being the bearing tree I find a number of blazed trees on either side of the line within the last 6100 chs. I therefore, at this point set a fir post 4 ins square 4 ft long 24 ins in the ground for S E cor of claim 38 from which fir 36 ins diam bears S 20°E 25 lks dist which I mark Cl. 38 A. T. A fir 24 ins diam bears West 44 lks dist marked Cl. 38 B. T.

Thence I run West on the South boundary of Claim 38. vs. 20°00' E.

3.00 Begin steep descent.

19.25 Foot of steep descent course N and S. On bench 400 ft. below S E Cor.

22.00 Begin steep descent to river.

24.00 To water's edge on East and left bank of river 50 ft below bench to determine the distance across I set a flag at this point on line and cross to right bank at the N E cor of claim 37 on line and from this point I measure a base South 5.00 chs to a point from which the flag bears N 62°E making the angle of the right angled triangle at this point 52- therefore the distance is $\tan 62 \times \text{base}$ or $1.880 \times 5.00 = 9.40$ chs which added to 24.00 makes

33.40 to the N E cor of claim 37

I again return to the N E cor of claim 38 to witness cor. Thence I run West on offset line.

3.00 to a point thence South 2.87 chs to North line of claim on account of the high water in the river the location of the witness cor. on the north boundary