

# County Surveyor's Record, Douglas County, Oregon

1908

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 22 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

A root hole, bears N.  $54\ 1/2^\circ$  W., 171 lks. dist., with a down fir alongside, 44 ins. diam., with no marks visible on open blaze.

At the corner point

Set an iron post, 28 ins. long,  $2\ 1/2$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 22 S R 9 W  
 $\frac{S\ 6}{S\ 7}$  S 8  
 1970

and bearing trees mkd. by persons unknown

A fir stump, 19 ins. diam., bears N.  $60\ 1/2^\circ$  E., 16 lks. dist., with partial scribe marks visible on bark blaze.

A fir, 13 ins. diam., bears S.  $80\ 1/2^\circ$  W., 29 lks. dist., with healed blaze.

and a new bearing tree

A fir, 13 ins. diam., bears N.  $50\ 1/2^\circ$  W., 39 lks. dist., mkd. T22S R9W S6 BT.

Land, mountainous.

Soil, clay loam.

Timber, fir, hemlock, cedar, alder, oak, and dogwood; undergrowth, salal, Oregon grape, hazel, fern and bunch grass.

---

Dependent Resurvey of a Portion of the Boundaries  
of Donation Land Claim No. 38, T. 22 S., R. 9 W.,  
Willamette Meridian, Oregon.

---

(Restoring the 1856 survey by Dennis Hathorn and the dependent resurvey by George S. Pershin in 1896.)

From the SW. cor. of Donation Land Claim No. 38, at proportionate distance along the N. bdy. of Claim No. 37; there is no remaining evidence of the original corner.

At the corner point

Set an iron post, 28 ins. long,  $2\ 1/2$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 22 S  
 S 18 C 38  
 R 9 W  
 C 37  
 1970

from which

An alder, 8 ins. diam., bears N.  $5\ 1/2^\circ$  E.,  $46\ 1/2$  lks. dist., mkd. C 38 BT.