

FIELD NOTES

T22 R9

DONATION LAND CLAIMS

CHAINS

T22S R9W DLC #39

25.00

The S E cor of claim 39 which is a stone 5 x 4 ins. 4 ins above the ground. The Oak now 18 ins diam bearing S 38°W 75 lks dist marked Cl. 39 is still standing the other bearing is gone. In its stead a fir 48 ins diam bears N 72°E 152 lks dist. I mark Cl. 39°

B. T. Thence I run North on East boundary of Claim 39 Va. 20°00'E.

3.25

A branch 12 lks wide course west

15.00

begin steep ascent.

22.00

Enter timber course E and W.

55.50

The N E Cor of claim 39 500 ft. above river A post has been set at this cor recently.

A fir 12 ins dia now about 30 ins dia bears S 89°W 35 lks. all grown over. had the new growth cut away leaving the original marks very distinct. The other a Fir 36 ins dia bears N 5°E 115 lks dist. Is distinctly marked on the bark.

November 20, 1896

Thence I run West on the North boundary of claim 39 . Va 20°00' E.

10.00

Begin steep descent.

46.20

Creek 25 lks wide course South.

46.75

Road course N and S to timber.

56.33

Can find no trace of post nor bearing trees set temp N W cor.

I now return to the witness corner at N E cor of claim 38 which is 20.62 chs north of the S W cor of claim 39, and which I have already chained in the measurement of claim 38.

(See page 10) Therefore

20.62

from S W cor to witness cor. on north bank of Umpqua river. Thence continue North on the West boundary of Claim 39.