


14448 County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 11, T. 23 S., R. 8 W.

CHAINS

Set an iron post, 28 ins. long, $2\frac{1}{8}$ ins. diam., 25 ins. in the ground, with brasscap marked



from which

A fir, 13 ins. diam., bears N. 16° W., 85 lks. dist., mkd. T23S R8W S11 CC BT.

A fir, 10 ins. diam., bears S. 79° W., 45 lks. dist., mkd. T23S R8W S11 CC BT.

Descend 40 ft. over SE. slope.

39.64 The center $\frac{1}{4}$ sec. cor. of sec. 11.

Descend 30 ft. over SE. slope.

40.70 Dirt road, 20 lks. wide, bears N. 80° E. and S. 80° W.

54.10 Bend of creek, 8 lks. wide, course S. 70° E. from SW.; desc. 5 ft. along creek bottom.

56.80 Same creek, course N. 65° E.

59.00 Same Creek, course S. 35° E.

60.60 Same creek, course N. 40° E.; asc. 5 ft. over NW. slope.

66.30 Dirt road, 15 lks. wide, bears N. 20° E. and S. 20° W.

68.20 Creek, 1 lk. wide, course N. 30° W.; asc. 70 ft. over NW. slope.

72.80 Dirt road, 20 lks. wide; bears N. and S.

75.60 Top of ascent, slopes N.; desc. 10 ft. along N. slope.

79.29 The $\frac{1}{4}$ sec. cor. of sec. 11 only, on the E. bdy. of sec. 11.

From the S $\frac{1}{16}$ sec. cor. of sec. 11 only, on the E. bdy. of sec. 11.

N. 89° 58' W., on the E. and W. center line of the SE $\frac{1}{4}$ of sec. 11.

Descend 60 ft. over W. slope, through heavy timber and dense undergrowth.

1.00 Dirt road, 15 lks. wide, bears N. and S.

3.00 Creek, 1 lk. wide, course N. 15° E.; asc. 445 ft. over general E. slope.

14.35 Spur, slopes N. 10° W.; desc. 305 ft. over broken NW. slope.

39.69 The center S $\frac{1}{16}$ sec. cor. of sec. 11.

From the W $\frac{1}{16}$ sec. cor. of secs. 11 and 14.

N. 0° 13' E., on the N. and S. center line of the SW $\frac{1}{4}$ of sec. 11.

Ascend 65 ft. over SE. slope, through heavy timber and dense undergrowth.