

Dependent Resurvey, Portion of W. Bdy., T. 29 S., R. 8 W.

CHAINS

from which

A fir, 8 ins. diam., bears N. $25\frac{1}{4}^{\circ}$ E., 12 lks.
dist., mkd. S31 BT.

A fir, 6 ins. diam., bears S. 41° W., $39\frac{1}{2}$ lks.
dist., mkd. S31 BT.

A fir, 11 ins. diam., bears N. 76° W. $25\frac{1}{2}$ lks.
dist., mkd. DLC 44 BT.

A fir, 13 ins. diam., bears N. $28\frac{3}{4}^{\circ}$ W., 25 lks.
dist., mkd. DLC 44 BT.

Reset the iron pipe alongside the iron post.

Descend 10 ft. over nearly level pasture land.

32.74 Wire fence and power line, bears N. 70° E. and S. 70° W.;
leave pasture.

33.24 Center line of Oregon State Highway No. 42, 35 lks. wide,
asphalt paving, bears N. 70° E. and S. 70° W.

33.54 Telephone line, bears Along highway; enter dense undergrowth.

40.58 The cor. of secs. 25, 30, 31 and 36, perpetuated and
recorded by James W. Byron, Deputy County Surveyor, in
1962, monumented with an iron post, $1\frac{1}{2}$ ins. diam.,
firmly set, extending 14 ins. above ground, with brass
cap mkd.

COUNTY SURVEYORS OFFICE

	T 29 S		
R	S 25	S 30	R
9	S 36	S 31	8
W			W
	1962		

from which the remains of the original SW. bearing tree:

An Oak snag, 40 ins. diam., bears S. 86° W., 319 lks.
dist., with no marks remaining on burned blaze,
remarked S36 CS T29S R9W BT on double blaze.
(Record, S. 88° W.)

and bearing trees marked by Byron

An ash, 8 ins. diam., bears N. $3\frac{3}{4}^{\circ}$ E., 66 lks.
dist., mkd. S30 CS BT on double blaze.

An Oak, 5 ins. diam., bears N. $23\frac{3}{4}^{\circ}$ W., 69 lks.
dist., mkd. S25 CS BT on double blaze.

No suitable bearing trees available within limits
in secs. 31 and 36.

Raise a mound of stone, $3\frac{1}{2}$ ft. base, 3 ft. high,
W. of the corner.

Land, rolling hills.

Soil, rocky clay.

Timber, fir, cedar, pine, madrone, maple, dogwood, oak,
yew, ash, chinquapin, alder, and hemlock; undergrowth,
salal, arrowwood, Oregon grape, huckleberry, blackberry,
willow, poison oak, vine maple, hazel, manzanita, vines,
and ferns.