

County Surveyor's Record, Douglas County, Oregon

Donation Land Claims of T 30 S., R. 4 W.

690c

CHAINS	
	<p><u>Claim #37</u></p> <p>Resurvey of Jacob Slippy Claim No. 37. Notification No. 143 in secs. 7, 18, and 19. T. 30 S. R. 4 W.</p> <p>Begin at a point 8. chns North of the 1/4 sec. cor. bet. secs 7 and 18, which is a cedar post, 3 ins square, firmly set in the ground, marked 1/4 S on N. face, from which a thorn 4 ins in diam bears N. 37 1/2° E., 79 lks. dist., marked 1/4 S. BT.</p> <p>On account of the County road, I set at a point 40 lks South of true corner, for witness corner to the NW. corner of this claim, a basalt stone 12 x 8 x 6 ins 9 ins in the ground, marked 37 W.C. on SW. face, thence run West, from true corner. Var 18°20' E.</p>
1.00	Left bank of the S. Umpqua river, course SW., line lies in river, set flagg W. on line on right bank, thence base South 7.00 chns. flagg bears N 63° W. making 13.73' across.
14.73	Right bank of river, rocky bottom.
16.50	Leave bottom, begin ascent, enter oak timber.
20.00	<p>Exterior angle corner. The old post marked T30 S R 4 W C1 37 set for this corner was standing, but decayed. I replace the same by setting an oak post 4 1/2 ft. long, 4 ins. square, 24 ins in the ground, marked T30S R4W C. 37 on E face, from which</p> <p>A wh. oak. 12 ins. in diam. bears S 25° E 70 lks. dist., marked T30S R4W C. 37 BT. This is the original bearing tree, whose marks being dim, I renew, thence</p> <p>South</p> <p>Descend through oak timber.</p>
4.00	Enter rocky bottom
7.30	Right bank of river, set flagg S. on line on left bank of river, run base West 200 chns, flagg bears S 24° E, making 4.49 chns across.
11.79	Left bank of river.
16.00	<p>Interior angle corner, the old post is gone and the bearing tree is washed away, I restore this corner by setting a fir post 4 1/2 ft. long, 4 ins. square, 24 ins in the ground marked T 30 S, R 4 W C. 37 on SE. face; no tree within limits, corner stands in orchard pit and therefore not made. Thence</p> <p>West</p>
2.00	Offset North 300 chns, on account of buildings.
5.61	Leave improvements, offset South 3.00 chns. regained true line, road to Canyonville, course S 60° W.
6.60	Left bank of river, course SW, set flagg W. on right bank fo river. on line, lay off base South 2.00 chns flagg bears N 74° W., making 698 lks across.
13.58	Right bank of river, enter rocky bottom.
16.50	Leave bottom, begin ascent of hill.
21.07	The NW. corner and West boundary of township 825 lks South of cor. to secs. 7, 18, 12 and 13. The post, set for this corner is gone, but the bearing tree is standing. I restore this corner by setting