

County Surveyor's Record, Douglas County, Oregon

713

CHAINS

Claim No. 47 cont.

88.00 NE corner. A post is standing in place but not the original, the bearing tree is also standing. The post being partly decayed, I restore this corner by setting a laurel post 4 1/2 ft. long, 4 ins. square, 24 ins. in the ground, marked T 30 S. R 4 W C. 47 on SW face from which the original tree,

A Bl. oak 30 ins. in diam. bears S 35° W., 102 lks. dist., marked T 30 S R 4 W C.47 BT.

Thence West on North boundary of Claim #47.

Var. 18° 5' E.

Through heavy underbrush, along S. slope of hill.

20.28 Intersected sec. line bet. secs. 3 and 4 2.08 chns North of cor. to secs. 3, 4, 10 and 9.

22.00 Begin descent; enter prairie.

36.20 Enter orchard, bears N. and S.

43.90 The N. W. corner. The old post is gone, and cultivation has obliterated all traces, on the ground. I am due South of NE. cor. of Claim No. 46. and on line with the SW. cor. of this claim. I restore this cor. by setting fir post 4 1/2 ft. long, 4 ins. square, 24 ins. in the ground, marked T 30 S, R. 4 W. C. 47 on the SE. face. Thence

South bet. claims 47 and No. 46.

Var. 18° 45' E.

1.84 Intersect sec. line bet. secs. 4 and 9. 16.07 chns. East of 1/4 sec. post bet. secs. 4 and 9.

40.28 N. E. corner of Claim No.44.

42.50 Begin ascent of West end of hill.

45.50 Top of rise, enter oak openings, begin descent.

54.24 Right bank of S. Umpqua river, course NW., set flagg South at SE. corner, run base East 260 lks. flagg bears S 25° 36' W., making 5.43 chns across.

59.67 Left bank of river, also S. E. cor. of Claim 44.

59.97 The SW. cor. or exterior angle corner, and place of beginning.

June 13, 1889