

# County Surveyor's Record, Douglas County, Oregon

T 30 S., R 4 W.

720

CHAINS

CLAIM NO. 50

Resurvey of Joseph P. Wilson's Land Claim No. 50. T. 30 S., R. 4 W in secs. 1, 2, and 12.

Begin at the SW. corner, 87 lks. N. and 21.17 chns. E. of the SW. cor. of sec. 2. The old post, set for this cor. is gone, but the stump of a Wh. oak, 28 ins. in diam. and corresponding in direction and distance with the field notes of original survey, furnished me, is standing, showing plainly the letters BT. I restore this corner by setting a basalt stone 18 x 12 x 8 ins. 12 ins. in the ground, marked 50 on the NE. face, from which

A Bl. oak 15 ins. in diam. bears N 71 1/2° E 324 lks. dist., marked T 30 S. R 4 W C.50 B.T.

Thence, North, bet. Claims No. 49 and 50.

Va. 18° 25' E.

Ascending a gentle S. slope.

17.10 NE. corner of Claim No. 49.

38.80 Leave field, enter oak openings.

40.00 The N.W. cor. The post set for this cor. is gone, but a stump of a Wh. oak, 24 ins. in diam.; and corresponding in direction and distance with the description in the field notes furnished me, and still showing surveyor marks, remains. I restore this corner by setting a cedar post 4 1/2 ft. long, 4 ins. square, 24 ins. in the ground, marked T 30 S R 4 W C.50 on SE. face, from which

A Bl. oak, 30 ins. in diam. bears S 60° E 368 lks. dist. marked T 30 S. R 4 W C.50 BT.

Thence, East on North boundary of Claim No. 50.

Var. 18° 35' E.

Descending through prairie with scattering oaks.

1.00 Enter grainfield.

23.00 A branch 2 lks. wide, course SE; enter lane leading SE to Chamberlin's house.

24.50 Enter grainfield, bears N & S.

47.25 A branch 4 lks. wide, course S 20° E.

58.00 Intersected sec. line bet. secs. 1 and 2, 2.00 chns N. of 1/4 sec. post.

75.40 Leave Chamberlin's field, enter Perdue's land.

80.00 NE cor. The post, set for this cor. is gone, the remains of an alder stump corresponding in size, direction and distance with the description of the field notes, furnished me, are on the branch. Mr. Perdue, who owns the land N. S. E and W. of this corner, and has lived here over 30 years, and who is present at this survey, is confident of its true location. I restore this cor. by setting a cedar post 4 1/2 ft. long, 4 ins. square, 24 ins. in the ground, marked T 30 S. R 4 W C.50 from which