

## Subdivisions of T. 20 S., R. 12 W.

CHAINS

furnished by the surveyor general.

Set a fir post at point for corner, 4 ft. long, 4 ins.

sq., 24 ins. in the ground, marked S  $7\frac{1}{4}$  S on the E. and  
S  $12\frac{1}{4}$  S on the W. faces.

This cor. is found to be N.  $5^{\circ}33'E.$ , 49.73 chs. from the  
cor. of secs. 12 & 13.

Thence I continue

North on E. bdy. of Sec. 12.

54.00 Top of spur on line, c W.; steep descent.

57.00 A creek, 2 lks. wide, c W.; steep ascent.

Top of spur on line, c W.; steep descent.

68.04 Intersect south shore of Lake Tsiltcoos. Unable to find  
any trace of meander cor. or witnesses thereto, re-  
establish a corner at this point by setting a willow  
post, 4 ft. long, 4 in. sq., 24 ins. in the ground,  
marked M C on the S., T 20 S on the N., R 11 W S 7 on  
the E. and R 12 W S 12 on the W. faces, for the meander  
cor. of fract. secs. 7 and 12 S. of lake and from which

A fir, 12 ins. diam., bears S.  $70^{\circ}E.$ , 14 lks. dist.,  
marked T 20 S R 11 W S 7 M C B T.

A fir, 10 ins. diam., bears S.  $30^{\circ}W.$ , 22 lks. dist.,  
marked T 20 S R 12 W S 12 M C B T.

I set a flag at this cor. and cross to N. side of lake  
and reestablish the meander cor. bet. secs. 1 and 12  
on W. margin of lake by setting a fir post, 4 ft. long,  
4 ins. sq., 24 ins. in the ground, and marked M C on the  
W., T 20 S R 12 W on the E., S 1 on the N. and S 12 on  
the S. faces; from which

A spruce, 5 ins. diam., bears S.  $21^{\circ}W.$ , 21 lks. dist.,  
marked T 20 S R 12 W S 12 M C B T.

An alder, 10 ins. diam., bears N.  $13^{\circ}E.$ , 14 lks.  
dist., marked T 20 S R 12 W S 1 M C B T.

The remains of the old witness trees are recognizable  
and are fully connected with this cor., as described  
in the notes furnished by the surveyor general.