

## Subdivisions of T. 20 S., R. 12 W.

## CHAINS

- 31.39 The meander post, starting point.
- 33.50 Enter swampy opening, c NW. and SE.
- 34.25 A creek, 4 lks. wide, c SE.
- 39.00 Leave swampy ground; enter timber, c N. & S.
- 40.00 Point for  $\frac{1}{4}$  sec. cor. Post gone, witnesses standing and agree with notes furnished by the surveyor general. Re-establish cor. from bearing trees.
- Set a fir post, 4 ft. long, 4 ins. sq., 24 ins. in the ground, marked S 34  $\frac{1}{4}$  S on the N. and S 3  $\frac{1}{4}$  S on the S. faces.
- Gradual ascent over hilly lands.
- 57.80 A spruce, 9 ft. diam., line tree.
- 75.00 Top of spur on line, c N.
- 79.60 Point for cor. of secs. 33 and 34. Cor. gone, marking on trees almost unperceptable. Re-establish the cor. from bearing trees, which agree with notes furnished by the surveyor general.
- Set a fir post, 4 ft. long, 4 ins. sq., 24 ins. in the ground, marked T 19 S R 12 W on the N., S 34 on the E., S 33 on the W. faces, also 3 notches each on E. and W. faces.
- 
- West, bet. secs. 4 and 33.
- 17.80 A creek, 1 lk. wide, c N.
- 21.90 A creek, 2 lks. wide, c NW.
- 26.50 Enter marsh, c N. and S.
- 29.50 Leave marsh, c N. and S.
- 40.45 Point for  $\frac{1}{4}$  sec. cor. Post gone, witnesses standing and agree with notes furnished by the surveyor general.
- Sept. 2nd, 1902.
- Over rolling and hilly lands.
- 80.80 Point for sec. cor. Cor. gone, witness trees standing and agree with notes furnished by the surveyor general.
- Re-establish cor. by setting a sandstone, 12x10x8 ins., 8 ins. in the ground, with 4 notches on the E. and 2