

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 20 S., R. 11 W.

CHAINS		
	North on line between secs. 35 and 36.	
	Var. 20° East.	
38.85	Top of dividing ridge, c E. & W.; begin steep descent.	+60
40.00	Set $\frac{1}{4}$ sec. post; from which	
	An alder, 9 in. in dia., bears N. 2° E., 128 lks. dist.	
	A cherry, 8 in. dia., bears S. 56 $\frac{1}{2}$ ° W., 30 lks. dist.	
47.60	Canyon, c W.; begin ascent.	-500
49.20	Top of spur, c E. & W.	+60
50.50	Canyon, c W.	-70
52.20	Fir, 36 in. in dia., top of rise; begin descent.	+40
54.00	Canyon, c W.; begin ascent.	-50
56.70	Fir, 36 in. in dia.	
60.50	Top of spur, c NNW. and SSE.	+300
64.00	Descend SW. slope.	
74.50	Canyon, c NW., bottom of canyon has a perpendicular rocky bank, 7 ft. high; begin ascent.	-350
78.80	Top of spur; begin descent.	+50
80.00	Set post for corner of secs. 36, 35, 26 and 25; from which	
	An alder, 8 in. in dia., bears N. 72° W., 28 lks.	
	An alder, 10 in. in dia., bears N. 53° E., 75 lks.	
	An alder, 12 in. in dia., bears S. 77 $\frac{1}{2}$ ° E., 60 lks.	
	A hemlock, 6 in. in dia., bears S. 21° W., 10 lks.	
	Nov. 28th, 1879.	
<hr/>		
	West, on random line, between sections 26 and 35.	
80.24	Intersect South 65 lks. of post to corner of secs. 35, 34, 26 and 27.	
	S. 89° 32' East, on true line, bet. secs. 26 & 35.	
	Descend. Var. 20° East.	
1.25	A canyon, c SE.; begin ascent of south slope of spur.	-40
7.00	Top of rise.	+50
14.50	Begin descent of NE. slope.	
22.00	Foot of hill; enter clearing.	-120
25.00	Bay's house door, bears S. 31° E.	