

Subdivisions of T. 20 S., R. 11 W.

CHAINS

- 85.10 Small clearing, bears W.
 85.75 Leave clearing; begin ascent.
 90.75 The cor. to secs. 5, 6, 7 & 8.

June 21st, 1892.

The line bet. cor. to secs. 5, 6, 31 and 32 and the $\frac{1}{2}$ sec. cor. bet. secs. 5 and 32 is short 2.50 chs., which error was caused by doubling the chain and keeping the same man ahead as chain bearer in front, so am I informed by Mr. Vanderburg, who assisted the deputy in running this line.

Meanders, T. 20 S., R. 11 W.

Meanders of Tsiltcoos Lake, now known popularly as Ten Mile Lake.

I begin at the meander cor. to frac. secs. 1 & 6, on West bdy. of Tp., which is a post, 4 ins. sq., badly decayed, marked M C on S., T 20 S on N., R 11 W S 6 on E., R 12 W S 1 on W. faces; from which

A spruce, 40 ins. dia., bears N.1°E., 238 lks. dist., marked T 20 S R 11 W S 6 M C B T.

The alder, 12 ins. dia., is gone. Fire has been through here, destroying most of the timber.

Thence I run with meanders in Sec. 6.

Var. 20° 20' E.

N. 85° E.,	2.27 chs.	Through marsh.
S. 12° W.,	4.50 "	
S. 20° W.,	5.00 "	
S. 27° W.,	7.50 "	
S. 57 $\frac{1}{2}$ ° W.,	2.50 "	To mouth of Fiddle Creek; thence up stream, along right bank.
N. 28° W.,	8.00 "	Through marsh.
N. 12 $\frac{1}{2}$ ° W.,	4.00 "	
N. 32 $\frac{1}{2}$ ° E.,	5.00 "	
N. 38° E.,	5.00 "	