

County Surveyor's Record, Douglas County, Oregon

Meanders, T. 20 S., R. 11 W.

CHAINS

S.51° W., 2.50 chs.
 S.38° W., 5.00 "
 S.11° E., 2.50 "
 S.26 $\frac{1}{2}$ ° E., 7.50 " Mouth of creek.
 S.86° E., 2.50 " Ten Mile Lake.
 S.74° E., 5.00 "
 S.36 $\frac{3}{4}$ ° E., 2.60 " To meander cor. to frac. secs.
 6 and 7.

Thence in Sec. 7.

Var. 20° 14' E.

S.20° W., 1.50 chs. Through marsh.
 N.86° W., 6.00 "
 S.30° W., 5.00 " Along foot of mountain.
 S.53° W., 5.00 "
 S.59° W., 4.00 "
 S.84 $\frac{1}{2}$ ° W., 4.08 " To meander cor. to frac. secs.

7 and 12, which is a post, 4 ins. sq., badly decayed,
 marked M C on N., R 11 W S 7 on E., R 12 W S 12 on W.,
 T 20 S on S. faces; from which

An alder stump, 8 ins. dia., bears S.76° E., 88 lks.
 dist., marked T 20 S R 11 W S 7 M C B T.

A spruce, 10 ins. dia., bears S.61° W., 42 lks. dist.,
 marked T 20 S R 12 W S 12 M C B T.

June 23rd, 1892.

Extracts from Field Notes of H. E. S. No. 190, situated
 in Siuslaw National Forest in Sec. 10, unsurveyed,
 T. 20 S., R. 11 W. as surveyed by Frederick W. Rase
 under Special Instructions dated Feb. 12, 1916.

Sept. 22, 1916: Preliminary to the survey of this home-
 stead entry, I make the following retracements:
 Commencing at the $\frac{1}{4}$ sec. cor. bet. secs. 3 and 10, which
 is a badly decayed post, marks not distinguishable,
 witnessed as described by the surveyor general.
 (Bearing trees decayed and down). I re-establish this
 $\frac{1}{4}$ sec. cor. in its original position as follows: