

County Surveyor's Record, Douglas County, Oregon

H. E. S. No. 190, T. 20 S., R. 11 W.

CHAINS

(The true bearing and length of the longitudinal  $\frac{1}{4}$  sec. line is S.0°06'W., 80.10 chs.)

September 22, 1916.

September 23, 1916: Commencing at the  $\frac{1}{4}$  sec. cor. bet. secs. 9 and 10, an alder tree, 14 ins. dia., down and badly decayed, but still showing markings. The bearing trees described by the surveyor general are also down. I reestablish this  $\frac{1}{4}$  sec. cor. in its original position, digging out the decayed tree, as follows:

Set a sandstone, 16x10x8 ins., 11 ins. in the ground, mkd.  $\frac{1}{4}$  on W. face; from which

A hemlock, 14 ins. dia., bears N.3°00'E., 168 lks. dist., mkd.  $\frac{1}{4}$  S 10 B T (new).

No other bearing tree available; raise a mound of stone, 3 ft. base, 2 ft. high,  $3\frac{1}{2}$  ft. dist. W. of cor.

Thence I run

S.89°54'E. (mean of N. and S. boundaries of W. half of sec. 10) on a true line, through center of Sec. 10.

\* \* \* \* \*