

County Surveyor's Record, Douglas County, Oregon

Meanders, T. 20 S., R. 10 W.

CHAINS

S.71 $\frac{1}{2}$ °E., .98 chains. The meander post on line between
secs. 27 & 28.

Thence on left bank in Sec. 27, from meander post on line
between secs. 27 & 28.

S.75° E., 3.00 chains.

S.70° E., 4.50 "

S.52 $\frac{1}{2}$ °E., .67 " The meander post on line between
secs. 27 & 34.

Meanders of right bank in Sec. 27, from meander post on
line between secs. 27 & 28.

East 4.00 chains.

S.50° E., 2.00 "

S.55° E., 6.80 " The meander post on line between
secs. 27 & 34.

Thence in Section 34, on left bank, from meander post on
line between secs. 27 & 34.

S.53° E., 2.50 chains.

S.65° E., 2.00 "

S.40° E., 1.50 "

S.20° E., 3.00 " At 50 lks. creek on opposite
side, 40 lks. wide.

E.4° E., 7.00 "

S.7° W., 8.00 " River, 210 lks. wide.

S.5° E., 4.00 "

South 10.00 "

S.23° E., 2.00 "

S.10° E., 5.00 " The head of navigation on Smiths
River. Up to this point the river is navigable for
vessels of 8 or 10 feet draught of water. The river
at this point is 200 lks. wide. I have not meandered
the right bank as the stream is narrow and of uniform
width.

Feb. 20th, 1867.