

County Surveyor's Record, Douglas County, Oregon

217

Subdivisions of T. 20 S., R. 10 W.
 Survey by Nathaniel Martin under Contract No. 599 dated
 June 20th, 1892.

CHAINS

- I go to the cor. of secs. 1, 2, 35, and 36, on S. bdy.
 and run
 N.1'W., bet. secs. 35 and 36, on random line.
 Va.19°E.
- 40.00 Set temp. $\frac{1}{4}$ sec. cor.
- 62.50 Here I find that high waters of Smith River and the
 cutting and burning of timber have entirely destroyed
 all traces and marks of the line and the witness cor.
 formerly established here; therefore, I continue my
 random line North 1' West.
- 80.30 Intersect E. & W. line at point 45 lks. W. of cor. of
 secs. 35, 36, 25, and 26, as determined by original
 bearing trees. The old post being destroyed, renewed
 the cor. by setting a post, 4 ft. long, 4 ins. sq., 24
 ins. in ground, marked T 20 S Sec 25 on NE., R 10 W Sec
 36 on SE., Sec 35 on SW., Sec 26 on NW. faces, 1 notch
 on S. and E. edges; from which a
 Fir, 36 ins. diam., bears N.50°E., dist. 20 lks.,
 marked T 20 S R 10 W Sec 25 B T.
 Fir, 4 ins. diam., bears S.67°E., dist. 26 lks.,
 marked T 20 S R 10 W Sec 36 B T.
 Maple, 4 ins. diam., bears S.50°W., dist. 21 lks.,
 marked T 20 S R 10 W Sec 35 B T.
 Maple, 5 ins. diam., bears N.42°W., dist. 26 lks.,
 marked T 20 S R 10 W Sec 26 B T.
- Thence I run
 South 18'W., on true line, between secs. 35 and 36.
 Va.19°E.
- Slight descent.
- 18.00 Right bank of Smith River, course W.
- 19.00 Left bank of Smith River; ascend steep hill.
- 40.00 Set post, 4 ft. long, 4 ins. sq., 24 ins. in the ground,
 for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S on W. face; from which a
 Hemlock, 36 ins. diam., bears S.20°E., dist. 21 lks.,
 marked $\frac{1}{4}$ S B T.