

County Surveyor's Record, Douglas County, Oregon

Resurvey of West Bdy. of T. 20 S., R. 10 W.

CHAINS

chs. on the N. bdy. of Sec. 19 bears N.89°58'E., 3.25 chs. dist.; I continued this line S.89°58'W., and at point of intersection

A cherry, 14 ins. diam., on line, which I marked T 20 S R 10 W C C on E., Sec 18 on N., Sec 19 on S., with 3 notches on N. & S. sides, for closing cor. to secs. 18 and 19; from which a

Chittem, 5 ins. diam., bears S.30°W., 22 lks. dist., marked T 20 S R 10 W C C Sec 18 & 19 B T.

Maple, 6 ins. diam., bears N.85°E., 60 lks. dist., marked T 20 S R 10 W Sec 18 B T.

Chittem, 6 ins. diam., bears S.76°E., 40 lks. dist., marked T 20 S R 10 W Sec 18 B T.

North on W. bdy. of Sec. 18.

Va.19°45'E.

Descend E. slope.

- 1.50 The established cor. to secs. 18, 19, 13 and 24, heretofore described in my subdivisional lines of the township. I destroyed all marks on this cor. relating to R. 10 W.
- 19.50 Stream, 20 lks., course E. and ascend through snow fall to green timber.
- 33.50 Spur, c SE.; along E. slope.
- 41.00 Canyon, course SW.
- 41.60 A post, 3 ft. long, 3 ins. sq., marked $\frac{1}{4}$ S on W. face, for $\frac{1}{4}$ sec. cor.; from which a
 - Fir, 12 ins. diam., bears S.12°W., 93 lks. dist., marked $\frac{1}{4}$ S B T.
 - Fir, 24 ins. diam., bears N.20°E., 35 lks. dist., marked $\frac{1}{4}$ S B T.
- 48.50 Spur, c E.
- 55.50 Spur, course S.80°E.
- 74.00 Ridge, course E. & W.

+300