

261

County Surveyor's Record, Douglas County, Oregon

Retracement of Portion North Bdy., T. 20 S., R. 10 W.

CHAINS

The cor. of secs. 4, 5, 32, and 33, on N. bdy. of T. 20 S., R. 10 W. bears N.89°39'W., 300.35 chs. dist.

The cor. of secs. 25, 26, 35, and 36, T. 19 S., R. 10 W., which is a fir post, 4 ins. sq., 12 ins. above ground, marked and witnessed as described by the surveyor general, bears N.42°6'W., 100.56 chs. dist.

The cor. of secs. 7, 12, 13, and 18, on W. bdy. of T. 20 S., R. 9 W., bears S.10°17'E., 128.30 chs. dist.

Retracement of Portion East Bdy., T. 19 S., R. 10 W. by Fred Mensch under Special Instructions dated Apr. 8, 1920.

The 1/4 sec. cor. on E. bdy. of sec. 36, T. 19 S., R. 10 W., originally a cherry, 8 ins. diam., is now dead, decayed and fallen. Both bearing trees also dead and down; marks legible on cor. and bearing trees. At exact cor. point, in cavity of decayed cor. tree,

Set a sandstone, 20x10x6 ins., 12 ins. in the ground, for 1/4 sec. cor. of sec. 36 only, marked 1/4 on W. side; from which (new bearing trees)

A cedar, 28 ins. diam., bears S.3°W., 153 lks. dist., marked 1/4 S 36 B T.

A chittem, 12 ins. diam., bears N.30°W., 95 lks. dist., marked 1/4 S 36 B T.

No iron posts available for this corner.

The cor. of secs. 25 and 36, on E. bdy. of T. 19 S., R. 10 W., which is a fir, 16 ins. diam., marked and witnessed as described by the surveyor general, bears N.0°04'W., 38.32 chs. dist.

From the 1/4 sec. cor.

South, retracing E. bdy. of Sec. 36.

Over mountainous land, through heavy timber and dense undergrowth, ascending 420 ft. on NE. slope.

13.30 Ridge, bears NW. and SE.; descend 150 ft. on SW. slope.

16.20 Ravine, course SW.; ascend 85 ft. on NW. slope.

20.50 Spur, slopes SW.; descend 200 ft. on SE. slope.