

County Surveyor's Record, Douglas County, Oregon

Resurvey of Portion East Bdy., T. 20 S., R. 10 W.

CHAINS

6 and 7, T. 20 S., R. 9 W.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor. of sec. 7 only, with brass cap marked

$\frac{1}{4}$
S7
1921

from which

An alder, 20 ins. diam., bears N.68°E., 55 lks. dist., marked $\frac{1}{4}$ S 7 B T.

A maple, 12 ins. diam., bears S.50°E., 39 lks. dist., marked $\frac{1}{4}$ S 7 B T.

Descend 100 ft. on S. slope to

30.41 Apportioned distance.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor. of sec. 12 only, with brass cap marked

$\frac{1}{4}$
S12
1921

from which

An alder, 18 ins. diam., bears S.66°W., 40 lks. dist., marked $\frac{1}{4}$ S 12 B T.

A fir, 40 ins. diam., bears N.25°W., 13 lks. dist., marked $\frac{1}{4}$ S 12 B T.

Descend 150 ft. on S. slope.

34.00 Ravine, course SE.; ascend 150 ft. on NE. slope.

45.00 Spur, slopes SE.; descend 200 ft. on S. slope.

48.00 Ravine, course E.; ascend 250 ft. on N. slope.

58.30 Spur, slopes E.; descend 60 ft. on S. slope.

60.81 Intersect the cor. of secs. 7, 12, 13, and 18, which is a chittim, 10 ins. diam., marked and witnessed as described by the surveyor general, except that the SE. and SW. bearing trees are dead. I replace these bearing trees.

From the corner