

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 20 S., R. 9 W.

CHAINS		
	2.88 chs.; N.25 $\frac{3}{4}$ °W., 3.70 chs.; N.35°W., 6.50 chs., intersect line, making 5.36 chs.	
7.56	Departure. Commence ascent.	
13.50	Top of rise, a bench.	+180
19.20	Gulch, c NW.	
23.00	Gulch, c N.	
23.20	Flat basin full of heavy undergrowth of salmonberries, dead alders, and firs.	+20
38.30	Gulch, c N.	
39.74	Set $\frac{1}{4}$ sec. post; from which A maple, 15 in. in dia., bears S.89°W., 69 lks. dist. A fir, 24 in. in dia., bears N.23°W., 60 lks. dist. Commence ascent.	
48.25	Top of spur, c N. and S.; commence descent.	+150
53.00	Top of spur, c N. and S.; descend now.	+100
62.00	Level flat.	-350
71.00	Fir, 54 in. in dia.	-20
77.00	Leave level flat and descend towards river.	
79.47	Intersect post to sections 29, 30, 31, and 32.	-10
	North, on line, between secs. 29 and 30. Var. 19 $\frac{1}{2}$ °E.	
2.60	Gulch, c W.	-20
10.20	Fir, 36 in. in dia.; edge of hemlock flat.	+30
16.95	Alder, 15 in. in dia. Commence descent.	
21.50	Low bottom.	-25
28.20	River bank. Chained across on rapids; about 4.00 chs. below the river turns abruptly S., course of same above is West.	
31.75	Right bank of river. Johnson's house bears N.66 $\frac{1}{4}$ °E.	
32.25	Trail, c SW. and NE.; commence ascent.	
35.92	Chitterwood, 16 in. in dia. Commence descending.	+40