

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 20 S., R. 9 W.

CHAINS		
39.60	Top of high sharp spur, c N.60°W. and S.60°E.; commence descent.	+6
40.35	Rocky bluff, 25 ft. high; keep on descending steep.	-60
43.10	Small bench.	-80
45.75	Rocky bluff, 20 ft. high; descend.	-50
47.25	Narrow bench; descending.	-100
52.85	Canyon, c SE.	-150
55.15	Top of rise; descend again.	+10
63.50	Enter flat bench.	-200
73.40	Commence descent.	
76.50	Trail, c S. and N.; enter bottom.	-40
77.25	To right bank of river, c S., 1.60 chs. wide.	
79.35	To post of corner to secs. 30, 31, 29 and 32.	+25

June the 16th, 1877.

West Bdy. of Tps. 20 and 21 S., R. 8 W. as surveyed by Wm. P. Wright under Contract 486 dated August 1, 1883.

North between secs. 1 & 6.

\*\*\*\*\*

80.00 Set post, 6 in. dia., 4 ft. long, 24 ins. in ground, for cor. to T. 20 & 21 S., Rs. 8 & 9 W., marked T 20 S S 31 on NE., R 8 W S 6 on SE., T 21 S S 1 on SW., R 9 W S 36 on NW. faces, with 6 notches on each edge; from which

A fir, 12 in. dia., bears N.61°W., 23 lks. dist., marked T 20 S R 9 W S 36 B T.

A fir, 12 in. dia., bears S.68°W., 31 lks. dist., marked T 21 S R 9 W S 1 B T.

A fir, 6 in. dia., bears S.31°E., 35 lks. dist., marked T 21 S R 8 W S 6 B T.

A dogwood, 6 in. dia., bears N.27°E., 19 lks. dist., marked T 20 S R 8 W S 31 B T.

North between secs. 31 & 36.

V.20°E.