

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 20 S., R. 9 W.

CHAINS

marked T 20 S R 9 W S 26 B T.

A cedar, 16 ins. diam., bears N.80 $\frac{1}{2}$ °W., 47 lks.dist.,

marked T 20 S R 9 W S 23 B T.

Oct. 10th, 1891.

N.89°42'W., on random line, bet. secs. 23 & 26.

Va.20°8'E.

40.00 Set temporary $\frac{1}{4}$ sec. cor.

80.60 Intersect N. & S. line, 42 lks. S. of cor. to secs. 22, 23, 26, and 27.

Thence I run

S.89°24'E., on true line, bet. secs. 23 & 26.

Va.20°2'E.

Descend E. slope.

3.00 A gulch, course S.; begin steep ascent.

-40

5.60 Top of spur, bears N. & S.; along S. slope.

+120

21.00 A branch, 2 lks. wide, course SW.

33.50 Top of spur, bears SW. and NE.

+100

40.30 Set a sandstone, 12x8x6 ins., 8 ins. in the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on N. face; raised a mound of stone, 1 $\frac{1}{2}$ ft. high, 2 ft. base, alongside. Pits impracticable. Burnt timber covering the ground.

47.75 A canyon, course NE.

-120

62.00 Top of spur, bears N. & S.

+240

67.50 A canyon, course S.; ascend S. slope, moderately steep.

-100

80.60 The cor. to secs. 23, 24, 25, and 26.

+80

Oct. 11th, 1891.

East, on true line, bet. secs. 24 & 25.

Va.20°8'E.

Ascend along S. slope, through fallen timber.

17.00 A canyon & branch, 2 lks. wide, course SW.; begin ascent.

-90

24.50 Top of spur, bears N. & S.; begin descent of SW. slope.

+160

29.25 A gulch & branch, 2 lks. wide, course S.; begin ascent.

-60

37.75 Top of spur, bears SW. and NE.; begin descent through fern.

+100