

Resurvey of S. Bdy. of T. 20 S., R. 9 W.

CHAINS

stroyed by floods.

I set alder post, 5 ft. long, 4 in. sq., 24 ins. in the ground, 15 lks. North of the right bank of Smiths River; post marked $\frac{1}{4}$ S on the N. face; from which

An alder, 8 ins. diam., bears N.3°30'W., 63 lks. dist., marked $\frac{1}{4}$ S B T.

An alder, 10 in. diam., bears S.82°W., 20 lks. dist., marked $\frac{1}{4}$ S B T.

44.00 Right bank of Smiths River; chained across.

64.25 Left bank of river, course N.80°W.; pass over rocky point.

81.40 The cor. to secs. 31 and 32. Old post greatly decayed, which I destroyed and set alder post, 4 ft. long, 4 ins. sq., 24 ins. in the ground, on side hill, sloping E., marked T 20 S S 32 on the NE. and R 9 W S 31 on the NW., with 5 notches on the E. and 1 notch on the W. edges; from which

A fir (stump) 50 ins. diam., bears S.71°15'E., 38 lks. dist., marked T 21 S R 9 W S 5 B T.

A fir, 60 ins. diam., bears S.27°W., 88 lks. dist., marked T 21 S R 9 W S 6 B T.

A maple, 36 ins. diam., bears N.66°30'W., 107 lks. dist., marked T 20 S R 9 W S 31 B T.

The bearing tree in Sec. 32 had been destroyed; I marked an alder, 6 ins. dia., bears N.16°45'E., 182 lks. dist., marked T 20 S R 9 W S 32 B T.

East, on the S. bdy. of Sec. 32.

Va.20°E.

Descend.

0.90 Buck Creek, 30 lks. wide, c North.

2.60 Leave creek bottom and ascend.

35.00 The $\frac{1}{4}$ sec. cor., which is a post, 2 ft. above ground, 3 ins. sq., marked $\frac{1}{4}$ S on the N. face; from which
A fir (stump), 36 ins. diam., bears N.64°E., 55 lks. dist., marked $\frac{1}{4}$ S B T.