

County Surveyor's Record, Douglas County, Oregon

Resurvey of S. Bdy. of T. 20 S., R. 9 W.

CHAINS

East on the S. bdy. of Sec. 35.

Var. 20° E.

Descend.

- 5.20 Scare Creek, 35 lks. wide, c North; ascend rocky ridge.
- 22.50 Top of ridge, sloping NW.; pass over cone.
- 37.60 The  $\frac{1}{4}$  sec. cor., which is a post, 3 ft. above ground, 2 ins. sq., marked  $\frac{1}{4}$  S on the N. face; from which
  - A maple, 6 ins. diam., bears N. 17° 30' E., 5 lks. dist., marked  $\frac{1}{4}$  S B T.
  - An alder, 12 ins. diam., bears S. 70° W., 40 lks. dist., marked  $\frac{1}{4}$  S B T.

Continued E. from the  $\frac{1}{4}$  sec. cor.

- 52.00 Creek, 3 lks. wide, c South; pass over spur. -150
- 59.00 Creek, 2 lks. wide, c SW.
- 77.60 The cor. to secs. 35 and 36, which is a fir stump,  $4\frac{1}{2}$  ft. in diam., marked T 20 S S 36 on the NE., R 9 W S 1 on the SE., T 21 S S. 2 on the SW. and S 35 on the NW. faces; from which

- A fir, 36 ins. diam., bears N. 81° E., 232 lks. dist., marked T 20 S R 9 W S 36 B T.
- A fir, 36 ins. diam., bears S. 81° 30' E., 177 lks. dist., marked T 21 S R 9 W S 1 B T.
- An elder, 5 ins. diam., bears N. 12° W., 8 lks. dist., marked T 20 S R 9 W S 35 B T.

The bearing tree in Sec. 2 had been destroyed.

The above bearing trees do not agree with notes furnished me by the U. S. Surveyor General.

October 9, 1894.

East on the South bdy. of Sec. 36.

Var. 20° E.

Pass over spur.

- 10.24 Creek, 1 lk. wide, c South. Pass over spur.
- 35.00 Creek, 2 lks. wide, c South.
- 39.20 To a point 67 lks. South of the  $\frac{1}{4}$  sec. cor., which is a