

County Surveyor's Record, Douglas County, Oregon

Resurvey of Subdivision Lines of T. 20 S., R. 9 W.

CHAINS

(New bearing tree) A fir, 40 ins. diam., bears S.20° W., 72 lks. dist., marked 1/4 S. 17 B T.

Thence

N.89°32'W.

Descend 50 ft. on SW. slope, to

1.79 Point at 40.00 chs. westing from cor. of secs. 8 and 9.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for 1/4 sec. cor. of sec. 8 only, with brass cap marked

1/4 S 8  
1921

from which

A fir, 60 ins. diam., bears N.30°E., 35 lks. dist., marked 1/4 S 8 B T.

A chitten, 8 ins. diam., bears N.63°W., 34 lks. dist., marked 1/4 S 8 B T.

Descend 200 ft. on W. slope.

11.00 Branch of Johnson Creek, 5 lks. wide, course S.; ascend 560 ft. on E. slope.

29.80 Spur, slopes SW.; descend 380 ft. on W. slope, to

39.40 Intersect true point for old cor. of secs. 7, 8, 17, and 18, determined by reference to the original bearing trees, which are as described by the surveyor general, except that the SE. bearing tree is dead. Hereafter this cor. will refer to secs. 17 and 18 only. I obliterate marks on former bearing trees referring to secs. 7 and 8, and at exact corner point.

Set an iron post, 3 ft. long, 2 ins. diam., 26 ins. in the ground, for cor. of secs. 17 and 18, with brass cap marked

T20S R9W  
S8  
S18 | S17  
T20S | R9W  
1921

from which

(New bearing tree) A vine maple, 6 ins. diam.,