

County Surveyor's Record, Douglas County, Oregon

North Bdy. of T. 21 S., R. 8 W.

CHAINS

N.89°49'E., on true line, between secs. 1 & 36.
 V.20°E.
 Ascend mountain..
 40.00 Set post, 4 ins. dia., 4 ft. long, with marked stone, 12
 ins. in ground, for gr. sec. cor., marked $\frac{1}{4}$ S on N.
 face; from which
 Fir, 4 ins. dia., bears N.30°W., 33 lks. dist.,
 marked $\frac{1}{4}$ S B T.
 Fir, 6 ins. dia., bears S.45°W., 15 lks. dist.,
 marked $\frac{1}{4}$ S B T.
 50.00 Top of mountain; descend..
 65.00 Branch, 8 lks. wide, flows South.
 80.00 The cor. to Townships 20. & 21 South, Range 8 West.
 Survey ended Sept. 11, 1883.

East Bdy. of T. 20 S., R. 8 W.
 Survey by Wm. P. Wright under Contract No. 486 dated
 Aug. 1st, 1883.

Finding that the East boundary of the township had not
 been run, I start from the closing cor. to Townships
 20 & 21 S., Range 8 West, which is a post, 4 ins. dia.
 in ground, marked T 21 S R 7 W S 6 on E., T 21 S R 8 W
 Sec 1 C C on SW., T 20 S R 8 W Sec 36 C C on NW. faces,
 with 6 notches in each edge; from which

Fir, 5 ins. dia., bears N.75°E., 11 lks. dist.,
 marked T 21 S R 7 W S 6 B T.

Maple, 24 ins. dia., bears N.75°W., 39 lks. dist.,
 marked T 20 S R 8 W S 36 B T C C.

Hemlock, 8 ins. dia., bears S.29°W., 14 lks. dist.,
 marked T 21 S R 8 W S 1 B T C C.

I run North on East boundary of Sec. 36.

V.19 $\frac{3}{4}$ °E.

19.75 The closing cor. to Tps. 20 & 21 S., R. 7 West.
 40.00 Set post, 4 ins. dia., 4 ft. long, with marked stone,
 12 ins. in ground, for gr. sec. cor., marked $\frac{1}{4}$ S on W.
 face; from which