

## County Surveyor's Record, Douglas County, Oregon

North Bay. of T. 20 S., R. 8 W.

CHAINS

Fir, 10 ins. dia., bears N.77°W., 33 lks. dist.,  
marked T 19 S. R 8 W S 35 B T.

N.89°47' East, on true line, bet. secs. 1 & 36.

V.20½°E.

Ascend.

35.00 Descend.

40.00 Set post, 4 ins. dia., 4 ft. long, with marked stone, 12  
ins. in ground, for qr. sec. cor., marked ¼ S on N.  
face; from which

Maple, 6 ins. dia., bears N.20°W., 31 lks. dist.,  
marked ¼ S B T.

Fir, 7 ins. dia., bears S.24°W., 10 lks. dist.,  
marked ¼ S B T.

43.00 Creek, 15 lks. wide, flows NW.; ascend.

80.00 The cor. to Town. 19 & 20 S., R. 8 West.

Survey ended Oct. 10th, 1883.

Subdivisions of T. 20 S., R. 8 W.  
Survey by Wm. F. Wright under Contract No. 486 dated  
August 1, 1883.

Survey commenced April 20th, 1884.

From the cor. to secs. 35, 36, 1 & 2, I run  
North between secs. 35 & 36.

V.20°E.

Along mountain, sloping W.

40.00 Set post; 4 ins. dia., 4 ft. long, with marked stone, 12  
ins. in ground, for qr. sec. cor., marked ¼ S on W.  
face; from which

Maple, 6 ins. dia., bears N.20°W., 30 lks. dist.,  
marked ¼ S B T.

Fir, 7 ins. dia., bears S.24°W., 10 lks. dist.,  
marked ¼ S B T.

60.00 Descend.

80.00 Set post, 6 ins. dia., 4 ft. long, with marked stone,  
12 ins. in ground, for cor. to secs. 25, 26, 35 & 36,