

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 20 S., R. 8 W.

CHAINS

S.89°41'East, on true line, between secs. 6 &amp; 7.

V.20½°E.

Along ridge.

58.60 Set post, 4 ins. dia., 4 ft. long, 12 ins. in ground, with marked stone, for qr. sec. cor., marked  $\frac{1}{4}$  S on N. face; from which

Fir, 24 ins. dia., bears S.15°W., 66 lks. dist., marked  $\frac{1}{4}$  S B T.

Fir, 20 ins. dia., bears N.21°W., 30 lks. dist., marked  $\frac{1}{4}$  S B T.

Along south slope of mountain; descend.

72.00 Branch, 8 lks. wide, flows S.; ascend.

98.60 The cor. to secs. 5, 6, 7 & 8.

---

North, on random line, between secs. 5 & 6.

V.20½°E.

40.00 Set temp. qr. sec. cor.

79.92 Intersect North bound. of Town., 35 lks. East of cor. to secs. 31, 32, 5 & 6; thence

S.15°East, on true line, bet. secs. 5 & 6.

39.92 Set post, 4 ins. dia., 4 ft. long, 12 ins. in ground, with marked stone, for qr. sec. cor., marked  $\frac{1}{4}$  S on W. face; raised mound of stone, 18 ins. high, 3½ ft. sqr. at base.

Descend gradually.

79.92 The cor. to secs. 5, 6, 7 & 8.

Survey ended May 20th, 1884.

---

Exteriors of T. 19 S., R. 8 W. as surveyed by Charles M. Collier under Contract No. 580 dated June 23rd, 1891.

East Bdy.

I begin at NE. corner of T. 20 S., R. 8 W., where found the post almost entirely burned. Set new post, 4½ ft. long, 4 ins. sq., 24 ins. in ground, marked T 20 S R 8 W S 1 on SW. and T 19 S R 8 W S 36 on NW. faces, with