

County Surveyor's Record, Douglas County, Oregon

South Bdy. of T. 19 S., R. 8 W.

CHAINS

In subdividing this Tp., failing to find the corners on the N. bdy. of T. 20 S., R. 8 W., from which I was instructed to start, except those on the N. line of Sec. 1 thereof, I started at the NW. cor. of said Sec. 1 and ran a trial line S.89°47'W., searching diligently and failing to find any of the corners and setting temp. $\frac{1}{4}$ sec. & sec. corners at every 40 & 80 chs., and at 417.30 chs. intersect the west boundary of said T. 20 S., R. 8 W., 10.45 chs. S. of NW. cor. of said Tp.; said trial line follows near old faintly blazed line. From said NW. cor. of said Tp. a strong line of blazes runs East about $\frac{1}{4}$ mile, but I could trace it no further. After diligent search I fail to find any other of the original marks of this line or any marks of lines coming in from the south.

It thus appearing that said line is not correctly run and that the true line bet. said NW. cor. Sec. 1, T. 20 S., R. 8 W. and the NW. cor. of said Tp. must run N.88°47'W., I return to said NW. cor. of Sec. 1, as appears set forth in notes of N. bdy. of T. 20 S., R. 8 W., and run

N.88°47'W., on true S. boundary of Sec. 35.

Va.20°35'E. at 11 a.m.

Near top of spur, course down N.70°E.

- 1.50 Descend.
- 17.00 Stream, 1 lk. wide, c N., 200 ft. below corner; ascend steep.
- 23.00 Top of divide, c S.70°E. & S.70°W., 300 ft. up; descend along N. slope.
- 30.00 Stream, 2 lks. wide, c N.20°E., 200 ft. down.
- 38.50 Divide, c NW: & SE., about 300 ft. up.
- 40.00 Stone in place, 36x24x8 ins. above ground, which I mark for $\frac{1}{4}$ sec. cor., $\frac{1}{4}$ S on N. face; from which
A fir, 30 ins. diam., brs. S.24°E., 119 lks. dist.,
marked $\frac{1}{4}$ S B T.