

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 19 S., R. 8 W.

CHAINS

- Descend very steep.
- 50.00 Into hollow, c E., about 300 ft. down; thence along East slope, very steep and rough.
- 58.25 A spur, c NE., about 300 ft. up; descend steep.
- 64.50 Stream, 1 lk. wide, c E., 150 ft. down; ascend along steep E. slope.
- 77.50 Onto ridge, c N.10°E., about 100 ft. up.
Va. by solar observation at 5 p.m. 20°35'E.
Descend very steep.
- 80.00 Set post, about 150 ft. below ridge, 4 ft. long, 4 ins. sq., 24 ins. in ground, for cor. to secs. 23, 24, 25, & 26, marked T 19 S S 24 on NE., R 8 W S 25 on SE., S 26 on SW., S 23 on NW. faces, with 2 notches on S. and 1 notch on E. edges; from which
- A cedar, 24 ins. dia., bears N.10°E., 41 lks. dist., marked T 19 S R 8 W S 24 B T.
 - A fir, 36 ins. diam., bears S.77°E., 127 lks. dist., marked T 19 S R 8 W S 25 B T.
 - A fir, 30 ins. diam., bears S.11½°W., 105 lks. dist., marked T 19 S R 8 W S 26 B T.
 - A fir, 50 ins. diam., bears N.70½°W., 68 lks. dist., marked T 19 S R 8 W S 23 B T.
-
- East, on random line, bet. secs. 25 & 24.
Va. at 5:30 p.m. 20°20'E.
In old deadening.
- 40.00 Set temp. $\frac{1}{4}$ S. cor.
Sept. 2nd, '91.
- 79.80 Intersect N. & S. line, at cor. to secs. 24 & 25.
Thence I run
West, on true line, bet. secs. 24 & 25.
Va. 20°35'E. at 8 a.m.
Descend gradually along S. slope.
- 15.00 Stream, 2 lks. wide, c S.20°W.; ascend.
- 20.00 Top of spur, c S.; descend steep.