

## County Surveyor's Record, Douglas County, Oregon

North Bdy. of T. 21 S., R. 7 W.

CHAINS

marked T 20 S R 7 W S 32 B T.

A fir, 36 ins. dia., bears S.32°E., 27 lks. dist.,

marked T 21 S R 7 W S 5 B T.

A fir, 40 ins. dia., bears S.63°W., 25 lks. dist.,

marked T 21 S R 7 W S 6 B T.

West, on a true line, on N. boundary Sec. 6.

V.21°E.

Descend.

- 7.50 Cross creek, 10 lks. wide, flows South; ascend.
- 30.00 On top hill; thence along North slope.
- 40.00 Set post, 4 ins. dia., 4 ft. long, 24 ins. in ground, for  
qr. sec. cor., marked  $\frac{1}{4}$  S on N. face; from which
- A fir, 70 ins. dia., bears S.45°W., 14 lks. dist.,  
marked  $\frac{1}{4}$  S B T.
- A fir, 16 ins. dia., bears N.10°E., 73 lks. dist.,  
marked  $\frac{1}{4}$  S B T.
- 80.00 Set temporary cor.

June 11, 1883.

West Bdy. of T. 21 S., R. 7 W.

I now start from the cor. Tps. 21 & 22 S., Rs. 7 & 8 W.;  
found post decayed & trees standing. Re-established  
the corner by setting a post, 4 $\frac{1}{2}$  ft. long, 4 $\frac{1}{2}$  ins. dia.,  
24 ins. in ground, for the cor. to Tps. 21 & 22 S., Rs.  
7 & 8 W., marked T 21 S S 31 on NE., R 7 W S 6 on SE.,  
T 22 S S 1 on SW., R 8 W S 36 on NW. face, with 6  
notches on each edge; from which

A hemlock, 8 ins. diam., bears N.55°E., 32 lks.  
dist., marked T 21 S R 7 W S 31 B T.

A cedar, 12 ins. diam., bears S.30°E., 28 lks. dist.,  
marked T 22 S R 7 W S 6 B T.

A cedar, 18 ins. diam., bears N.30°W., 55 lks. dist.,  
marked T 21 S R 8 W S 36 B T.

A cedar, 12 ins. diam., bears S.40°W., 50 lks. dist.,