

County Surveyor's Record, Douglas County, Oregon

North Bdy. of T. 20 S., R. 7 W.

CHAINS		
	S., R. 7 W.	
	Va. 21°25'E.	
3.73	A fir, 65 ins. dia., on line, with 2 notches on E. & W. sides.	
8.85	A fir, 60 ins. dia., which I marked with 2 notches on E. & W. sides.	
10.00	Stream, 6 lks. wide, c S.40°E.	-175
17.50	Va. 21°30'E.	
20.00	A fir, 40 ins. dia., on line, which I marked with 2 notches on E. & W. sides.	
22.25	Top of spur, c N.80°E.	+200
26.75	Canyon, c NE.	
35.25	Spur, c N.10°E.	
36.25	Descend slightly.	
39.55	Canyon, c N.	-150
40.00	Set chitten post, 4 ft. long, 4 ins. square, 24 ins. in the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S on N. face; from which A cedar, 24 ins. dia., bears S.81°E., 45 lks. dist., marked $\frac{1}{4}$ S.B T. A fir, 12 ins. dia., bears N.40°W., 9 lks. dist., marked $\frac{1}{4}$ S B T.	
47.50	Top of ridge, c N.76°W.	+100
57.40	Fir, 60 ins. dia., on line, which I mark with 2 notches on E. & W. sides.	
65.00	Divide, c S.76°W.	+100
72.50	Ridge, c N.; descend.	
80.00	(Note: I here set a cor. common to 4 sections, but after I found the errors in the E. bdy. of the township, through which I found it necessary to set closing corners on the N. bdy. of the township, thus making this corner, as well as the cor. to secs. 31 & 32 common only to 2 sections each, I returned to this corner and Set a maple post, 4 ft. long, 4 ins. square, 24 ins. in the ground, for cor. to secs. 32 & 33, marked T 19 S R	