

County Surveyor's Record, Douglas County, Oregon

West Bdy. of T. 20 S., R. 7 W.

CHAINS

Va. 21°15'E.

21.00 To a point 75 lks. West of the $\frac{1}{4}$ sec. cor. to sec. 36, which is a post, 4 ins. diam., 2 ft. above ground and marked $\frac{1}{4}$ S on W. face; from which

A fir, 48 ins. diam., bears W., 25 lks. dist., marked $\frac{1}{4}$ S B T.

A fir, 36 ins. diam., bears S.60°E., 36 lks. dist., marked $\frac{1}{4}$ S B T.

27.30 A stream, 3 lks. wide, c W.

61.50 To a point 210 lks. West of the cor. to secs. 25 & 36, which is a post, 6 ins. diam., firmly set in the ground and marked T 20 S R 7 W S 31 on E., T 20 S R 8 W C C S 36 on SW., S 25 on NW. faces, with 1 notch on S. & 5 notches on North edge; from which

A fir, 24 ins. dia., bears N.54°E., 58 lks. dist., marked T 20 S R 7 W S 31 B T.

A maple, 16 ins. dia., bears N.77°W., 12 lks. dist. (not 72 lks.), marked T 20 S R 8 W S 25 B T C C.

A fir, 24 ins. dia., bears S.17°W., 73 lks. dist., marked T 20 S R 8 W S 36 B T C C.

The bearing of this line is, therefore, N.1°58'E. and the township west having been subdivided, I could not change this line.

Sept. 14, 1891.

Then offset E. 2.10 chs. to cor. and run N. on a true line, E. bdy. Sec. 25, T. 20 S., R. 8 W.

Va. 21°15'E.

7.20	Ridge, c NW. & SE.	+300
17.00	Canyon, c E.	+100
39.00	Cross ridge, c SE.; descend.	
40.00	To a point 68 lks. west of a post, 6 ins. diam., firmly set in the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S on W. face; from which	
	A fir, 20 ins. dia., bears S.72°E., 21 lks. dist., marked $\frac{1}{4}$ S B T.	