

County Surveyor's Record, Douglas County, Oregon

West Bdy. of T. 20 S., R. 7 W.

CHAINS

A fir, 20 ins. dia., bears S.87°W., 31 lks. dist.,
marked $\frac{1}{4}$ S B T.

79.30 To a point 140 lks. West of a post, firmly set in the
ground, 5 ins. dia., for cor. to secs. 24 & 25, marked
T 20 S R 7 W S 30 on E., T 20 S R 8 W S 25 C C on SW.,
S 24 C C on NW. faces, with 2 notches on S. and 4
notches on N. edges; from which

A fir, 12 ins. diam., bears S.31°E., 21 lks. dist.,
marked T 20 S R 7 W S 30 B T.

A fir, 30 ins. diam., bears N.47°W., 71 lks. dist.,
marked T 20 S R 8 W S 24 B T.

A fir, 30 ins. diam., bears S.71°W., 77 lks. dist.,
marked T 20 S R 8 W S 25 B T.

Therefore the true bearing of the E. bdy. of Sec. 25 is
N.1°E.

Sept. 15, 1891.

I here offset E. 140 lks. to cor.; thence I run
N. on E. bdy. Sec. 24, T. 20 S., R. 8 W.

Va.21°E.

Along W. slope of ridge.

.70 Stream, 3 lks. wide, c W.

37.25 Stream, 2 lks. wide, c W.

40.20 To a point 70 lks. west of a post, 4 ins. square, firmly
set in the ground, for $\frac{1}{4}$ sec. cor.; from which

A cedar, 14 ins. dia., bears S.53°W., 12 lks. dist.,
marked $\frac{1}{4}$ S B T.

A cedar, 20 ins. dia., bears N.62°E., 24 lks. dist.,
marked $\frac{1}{4}$ S B T.

57.75 Stream, 6 lks. wide, c W.

79.75 To a point 140 lks. West of a post, 6 ins. dia., firmly
set in the ground, for cor. to secs. 13 & 24, marked
T 20 S R 7 W S 19 on E., T 20 S R 8 W S 24 C C on SW.,
S 13 C C on NW. faces, with 3 notches on N. & S. edges;
from which

-75