

## East Bdy. of T. 20 S., R. 7 W.

CHAINS	Along side of canyon on W. slope; descend.	
78.37	Spur, c N.20°W.; still descending.	-180
80.00	Set post, 5 ft. long, 4 ins. square, 24 ins. in the ground, for cor. to secs. 13 & 24, marked T 20 S R 7 W on W., S 13 on N., S 24 on S. faces, with 3 notches on N. & S. faces; from which A cedar, 5 ins. dia., bears N.8°W., 12 lks. dist., marked T 20 S R 7 W S 13 B T. A chittem, 7 ins. dia., bears S.44°W., 25 lks. dist., marked T 20 S R 7 W S 24 B T. A cedar, 4 ins. dia., bears N.50°E., 15 lks. dist., marked T 20 S R 7 W S 13 & 24 B T. Aug. 28, 1891.	
<hr/>		
	N. on true line, E. bdy. Sec. 13. Va.20°45'E.	
1.62	Stream, 3 lks. wide, c N.75°W.	-100
2.93	The cor. to secs. 19 & 18, where I find post and part of witness trees decayed. I reestablish this cor. by setting a new post, 4 ft. long, 4 ins. square, 24 ins. in the ground where the old post was standing, marked T 20 S R 6 W on E., S 18 on N., S 19 on S. faces, with 3 notches on N. & S. faces, and mark the following witness trees: A fir, 40 ins. dia., bears N.5°E., 60 lks. dist., marked T 20 S R 6 W S 18 B T. A fir, 48 ins. dia., bears S.82°W., 35 lks. dist., marked T 20 S R 6 W S 18 & 19 B T. A hemlock, 28 ins. dia., bears S.63°E., 35 lks. dist., marked T 20 S R 6 W S 19 B T. In running North from this cor. I found no blazes or marks whatever; I, therefore, blazed a new line.	
8.43	Ridge, c W.	+80
9.90	Stream, 2 lks. wide, c W.	-100
19.40	Panther Creek, 12 lks. wide, c S.6°W.	