

County Surveyor's Record, Douglas County, Oregon

East Bdy. of T. 20 S., R. 7 W.

CHAINS 20.13	Panther Creek, 12 lks. wide, c S.10°E.	
21.93	Panther Creek, 12 lks. wide, c S.35°W.	
26.93	Stream, 2 lks. wide, c S.35°E.	
38.93	Spur, c S.45°E.	+150
40.00	Set post, 4 ft. long, 4 ins. square, 24 ins. in the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S on W. face; from which A fir, 10 ins. dia., bears E., 36 lks. dist., marked $\frac{1}{4}$ S B T. A fir, 20 ins. dia., bears N.67°W., 64 lks. dist., marked $\frac{1}{4}$ S B T.	
46.15	Stream, 2 lks. wide, c S.50°E.	-100
59.90	Spur, c S.45°E.	+250
66.40	Spur, c E.	
70.40	Canyon, c E.	
78.90	Top of spur, c E.; descend.	+200
80.00	Set post, 4 ft. long, 4 ins. square, 24 ins. in the ground, for cor. to secs. 12, 13, 7 & 18, marked T 20 S S 7 on NE., R 6 W S 18 on SE., R 7 W S 13 on SW., S 12 on NW. faces, with 4 notches on S. & 2 notches on N. edges; from which A fir, 20 ins. diam., bears N.27°E., 60 lks. dist., marked T 20 S R 6 W S 7 B T. A maple, 4 ins. diam., bears S.87°E., 14 lks. dist., marked T 20 S R 6 W S 18 B T. A fir, 20 ins. diam., bears S.23°W., 38 lks. dist., marked T 20 S R 7 W S 13 B T. A fir, 24 ins. dia., bears N.30°W., 9 lks. dist., marked T 20 S R 7 W S 12 B T.	

Aug. 29, 1891.

Subdivisions of T. 20 S., R. 7 W.
Survey by Thos. E. Todd under Contract No. 574 dated
May 19th, 1891.

I commence at the cor. to secs. 35 & 36, on S. bdy. of
Township; thence I run
N.0°1'W., on line bet. secs. 35 & 36.