

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 20 S., R. 7 W.

CHAINS

marked T 20 S R 7 W C C S 4 & 5 B T.

Oct. 23, 1891.

	From the cor. to secs. 31 & 32, on the S. bdy. of the township, I run	
	N.0°4'W., bet. secs. 31 & 32.	
	Va.21°15'E.	
2.50	Canyon, c E.	-75
5.00	Spur, c SE.; thence along E. slope.	+75
19.00	Avalanche Creek, 4 lks. wide, c SE.; ascend.	-100
40.00	Set a post, 4 ft. long, 4 ins. square, 24 ins. in the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S on W. face; from which	
	A fir, 48 ins. dia., bears S.66°E., 44 lks. dist., marked $\frac{1}{4}$ S B T.	
	A fir, 66 ins. dia., bears S.88°W., 38 lks. dist., marked $\frac{1}{4}$ S B T.	
50.20	Top of high divide, c E. & W.; descend along W. side of ridge in canyon with slide.	+150
80.00	Set a sandstone, 20x12x10 ins., 16 ins. in the ground, for cor. to secs. 29, 30, 31 & 32, marked with 1 notch on S. & 5 notches on E. edges; from which	
	A cedar, 18 ins. dia., bears N.3°E., 24 lks. dist., marked T 20 S R 7 W S 29 B T.	
	A cedar, 36 ins. dia., bears S.87°E., 37 lks. dist., marked T 20 S R 7 W S 32 B T.	
	A cedar, 30 ins. dia., bears S.8°W., 68 lks. dist., marked T 20 S R 7 W S 31 B T.	
	A cedar, 20 ins. dia., bears N.74°W., 120 lks. dist., marked T 20 S R 7 W S 30 B T.	
	Sept. 12, 1891.	

N.89°30'E., on a random line, bet. secs. 29 & 32.

Va.21°15'E.

40.00 Set temporary $\frac{1}{4}$ sec. cor.