

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 21 S., R. 7 W.

CHAINS

marked T. 21 S R 7 W S. 15 B T.

Fir, 40 ins. dia., bears S. 57° W., 27 lks. dist.,

marked T 21 S R 7 W S 16 B T.

Fir, 36 ins. dia., bears N. 69° W., 44 lks. dist.,

marked <sup>4</sup> 21 S R 7 W S 9 B T.

East, on random line, between secs. 10 & 15.

V. 21° E.

40.00 Set temp. gr. sec. cor.

80.30 Intersect N. & S. line, 35 lks. South of cor. to secs. 10,  
11, 14 & 15.

Thence S. 89° 45' West, on true line, between secs. 10 & 15.

Descend.

3.50 Gulch; ascend.

17.50 Cross ridge, NW. & SE.; descend.

27.50 Gulch; ascend.

34.50 Ridge; descend.

40.15 Set post, 6 ins. dia., 4 ft. long, with marked stone, 12  
ins. in ground, for gr. sec. cor., marked  $\frac{1}{2}$  S on N.  
face; from which

Fir, 20 ins. dia., bears S. 18° E., 25 lks. dist.,  
marked  $\frac{1}{2}$  S B T.

Fir, 18 ins. dia., bears N. 52° E., 18 lks. dist.,  
marked  $\frac{1}{2}$  S B T.

61.50 Cross branch, 6 lks. wide, flows N.; ascend.

80.30 The cor. to secs. 9, 10, 15 & 16.

June 29, 1883.

Subdivisions of T. 21 S., R. 7 W.  
Survey by Wm. P. Wright under Contract No. 514 dated  
August 27th, 1884.

Survey commenced Sept. 9th, 1884 at the cor. to secs. 9,  
10, 15 & 16, which is a post, 6 ins. dia., in ground,  
marked T 21 S S 10 on NE., R 7 W S 15 on SE., S 16 on  
SW., S 9 on NW. face, with 3 notches on E. and 4 on  
South edges; from which